



### Hardness Correlation Table

Shore						Pusey and Jones
A	B	C	D	O	OO	
100	85	77	58			0-3
95	81	70	46			10-15
90	76	59	39			20-25
85	71	52	33			35-40
80	66	47	29	84	98	45-50
75	62	42	25	79	97	60-65
70	56	37	22	75	95	70-75
65	51	32	19	72	94	80-90
60	47	28	16	69	93	90-100
55	42	24	14	65	91	110-120
50	37	20	12	61	90	120-130
45	32	17	10	57	88	140-150
40	27	14	8	53	86	160-170
35	22	12	7	48	83	180-200
30	17	9	6	42	80	200-240
25	12			35	76	
20	6			28	70	
15				21	62	
10				14	55	
5				8	45	

Information contained in all our data sheets is, to the best of our knowledge, true and accurate. Since conditions of use are beyond our control, no warranty is given or implied in respect of any recommendations or suggestions made by ourselves, nor is freedom from patent infringement inferred.